CIBO Spirabands & Arbors

Abrasive sleeves and matching mounting hardware



Choose by the Job

Application	Choose	Page
Cylindrical Zirconia	SHS	2
Cylindrical Ceramic	SHS	3
Cylindrical Aluminium Oxide	SHS	4
Conical Zirconia	SHC	5
Flexible Aluminium Oxide	SHE	6
Short aluminium-oxide sleeves	SHS /A	7
Rubber arbors	SHSH, SHCH, SHEH	8

Match the Tool and Holder

Use a holder that matches the mounting and size. Follow the lowest maximum speed shown on the disc, holder or tool.

R H Davey Welding Supplies Ltd · 023 8033 9443 · sales@rhdaveywelding.co.uk
67–69 Quayside Road, Southampton SO18 1AE

© R H Davey Welding Supplies Ltd · Design and editorial content

CIBO ORDERING GUIDE

Cylindrical Zirconia

Order by diameter × working length and grit. Use the arbor specified for the sleeve profile.



SHS

SHS zirconia for weld dressing, deburring and shaping on curves and radii.

Size	CIBO order codes	Matching arbor
10 × 20mm	SHS/40/1020 / SHS/60/1020 / SHS/80/1020 / SHS/150/1020	SHSH1020
15 × 30mm	SHS/40/1530 / SHS/60/1530 / SHS/80/1530 / SHS/150/1530	SHSH1530
22 × 20mm	SHS/40/2220 / SHS/60/2220 / SHS/80/2220 / SHS/150/2220	SHSH2220
30 × 30mm	SHS/40/3030 / SHS/60/3030 / SHS/80/3030 / SHS/150/3030	SHSH3030
45 × 30mm	SHS/40/4530 / SHS/60/4530 / SHS/80/4530 / SHS/150/4530	SHSH4530
60 × 30mm	SHS/40/6030 / SHS/60/6030 / SHS/80/6030 / SHS/150/6030	SHSH6030

CIBO technical reference

© R H Davey Welding Supplies Ltd · Design and editorial content

CIBO ORDERING GUIDE

Cylindrical Ceramic

Order by diameter × working length and grit. Use the arbor specified for the sleeve profile.



SHS

SHS ceramic for heavier material removal on steel and stainless steel.

Size	CIBO order codes	Matching arbor
10 × 20mm	SHS/40/1020/K / SHS/60/1020/K / SHS/80/1020/K / SHS/120/1020/K	SHSH1020
15 × 30mm	SHS/40/1530/K / SHS/60/1530/K / SHS/80/1530/K / SHS/120/1530/K	SHSH1530
22 × 20mm	SHS/40/2220/K / SHS/60/2220/K / SHS/80/2220/K / SHS/120/2220/K	SHSH2220
30 × 30mm	SHS/40/3030/K / SHS/60/3030/K / SHS/80/3030/K / SHS/120/3030/K	SHSH3030
45 × 30mm	SHS/40/4530/K / SHS/60/4530/K / SHS/80/4530/K / SHS/120/4530/K	SHSH4530
60 × 30mm	SHS/40/6030/K / SHS/60/6030/K / SHS/80/6030/K / SHS/120/6030/K	SHSH6030

CIBO technical reference

© R H Davey Welding Supplies Ltd · Design and editorial content

CIBO ORDERING GUIDE

Cylindrical Aluminium Oxide

Order by diameter × working length and grit. Use the arbor specified for the sleeve profile.



SHS

Long aluminium-oxide sleeves for woodworking and shaping.

Size	CIBO order codes	Matching arbor
20 × 120mm	SHS/40/20120 / SHS/60/20120 / SHS/80/20120 / SHS/120/20120	Confirm exact holder
25 × 120mm	SHS/40/25120 / SHS/60/25120 / SHS/80/25120 / SHS/120/25120	Confirm exact holder
30 × 120mm	SHS/40/30120 / SHS/60/30120 / SHS/80/30120 / SHS/120/30120	Confirm exact holder
35 × 120mm	SHS/40/35120 / SHS/60/35120 / SHS/80/35120 / SHS/120/35120	Confirm exact holder
45 × 120mm	SHS/40/45120 / SHS/60/45120 / SHS/80/45120 / SHS/120/45120	Confirm exact holder
50 × 120mm	SHS/40/50120 / SHS/60/50120 / SHS/80/50120 / SHS/120/50120	Confirm exact holder
40 × 120mm	SHS/40/40120 / SHS/60/40120 / SHS/80/40120 / SHS/120/40120	Confirm exact holder

CIBO technical reference

Long Sleeve Mounting

The 120mm sleeves require a matching long support. Confirm the holder before ordering.

© R H Davey Welding Supplies Ltd · Design and editorial content

CIBO ORDERING GUIDE

Conical Zirconia

Order by diameter × working length and grit. Use the arbor specified for the sleeve profile.

SHC



SHC tapered sleeves for reaching into shaped work and finishing internal radii.

Size	CIBO order codes	Matching arbor
22 → 29 × 30mm	SHC/40/2230 / SHC/60/2230 / SHC/80/2230 / SHC/120/2230	SHCH2230
22 → 36 × 60mm	SHC/40/2260 / SHC/60/2260 / SHC/80/2260 / SHC/120/2260	SHCH2260

CIBO technical reference

© R H Davey Welding Supplies Ltd · Design and editorial content

CIBO ORDERING GUIDE

Flexible Aluminium Oxide

Order by diameter × working length and grit. Use the arbor specified for the sleeve profile.



SHE

SHE flexible sleeves for conforming to a surface with the matching extra-soft arbor.

Size	CIBO order codes	Matching arbor
75 × 30mm	SHE/60/7530 / SHE/80/7530 / SHE/120/7530 / SHE/150/7530 / SHE/180/7530 / SHE/220/7530	SHEH7530

CIBO technical reference

© R H Davey Welding Supplies Ltd · Design and editorial content

CIBO ORDERING GUIDE

Short Aluminium-Oxide Sleeves

Small cylindrical sleeves for controlled sanding on profiles and in tight spaces.



SHS · Aluminium Oxide

Use P80 for general sanding and P150 for refinement. These additional sizes are listed for UK supply.

Size	CIBO order codes	Arbor order reference
10 × 10mm	SHS/80/1010/A / SHS/150/1010/A	SHSH/1010
13 × 25mm	SHS/80/1325/A / SHS/150/1325/A	SHSH/1325
15 × 10mm	SHS/80/1510/A / SHS/150/1510/A	SHSH/1510
19 × 25mm	SHS/80/1925/A / SHS/150/1925/A	SHSH/1925
25 × 25mm	SHS/80/2525/A / SHS/150/2525/A	SHSH/2525

© R H Davey Welding Supplies Ltd · Design and editorial content

CIBO ORDERING GUIDE

Rubber Arbors

Match the rubber head to the sleeve diameter, length and profile. Check the spindle diameter against the tool collet.



SHSH · Hard Cylindrical

Use the matching sleeve profile. Check the holder markings for its speed limit.



Head size	Spindle	CIBO order code
10 × 20mm	6mm	SHSH1020
22 × 20mm	6mm	SHSH2220
15 × 30mm	6mm	SHSH1530
30 × 30mm	6mm	SHSH3030
45 × 30mm	6mm	SHSH4530
60 × 30mm	6mm	SHSH6030
10 × 10mm	6mm	SHSH/1010
13 × 25mm	6mm	SHSH/1325
15 × 10mm	6mm	SHSH/1510
19 × 25mm	6mm	SHSH/1925
25 × 25mm	6mm	SHSH/2525
5 × 12.5mm	6mm	SHSH/5125



SHCH · Hard Conical

Use the matching sleeve profile. Check the holder markings for its speed limit.

Head size	Spindle	CIBO order code
22 × 30mm	6mm	SHCH2230
22 × 60mm	6mm	SHCH2260



SHEH · Extra Soft Cylindrical

Use the matching sleeve profile. Check the holder markings for its speed limit.



Head size	Spindle	CIBO order code
45 × 30mm	Confirm	SHEH4530
60 × 30mm	Confirm	SHEH6030
75 × 30mm	6mm	SHEH7530
100 × 40mm	8mm	SHEH10040

© R H Davey Welding Supplies Ltd · Design and editorial content