JASIC / PLASMA / EVO

EVO CUT 80

AIR PLASMA CUTTING

External air supply

EP-80



Where it fits

For three-phase cutting with a 25mm clean-cut rating. Choose the external-air model for a workshop or CNC installation with a suitable air supply.

- Non-HF pilot ignition and mesh mode for interrupted material.
- 14-pin CNC interface for compatible mechanised setups.
- Digital control with adjustable post-flow and gas check.

Package and options

ITEM	DETAIL
Included	6m UPH-125 Cutting Torch (05921CX), 3m Earth Clamp
Options	Compressor (AP-140), Trolley (TR-03), 14 Pin CNC Plug (51006273), Circle Cutting Kit (51865)
For repeat shapes	Use the circle-cutting kit for round blanks. Specify a machine torch where the setup calls for CNC mounting and Jasic lists one.

Output and setup data

RATING	VALUE
Input supply	400 V AC, three-phase
Cutting output	20–80 A
Duty at 40°C	80 A at 40%
Clean cut	25mm
Severance	35mm
Pierce cut	20mm
Air supply	200 L/min at 5 bar
Rated input power	12.5 kVA
Protection	IP23S
L × W × H	626 × 230 × 416mm
Weight	22 kg

Cut ratings are for carbon steel. For CNC, confirm the limit for the table and torch combination. Use the clean-cut rating for sizing the machine. Severance is the limit for separating the material.

Jasic technical reference

Jasic product information

© R H Davey Welding Supplies Ltd · Design and editorial content